

From:

Cooper Restorations
5304 S Adams
Marion, IN 46953
cooperrestorations@gmail.com

| | |
|------------------|-------------------|
| Invoice Number | CR-2131 |
| Order Number | 8561 |
| Invoice Date | November 19, 2021 |
| Total Due | \$1,644.60 |

Billing address

Terry McFarland

| Hrs/Qty | Service | Rate/Price | Sub Total |
|---------|---|------------|-----------|
| 1 | 71-72 C10 outer grille | \$335.00 | \$335.00 |
| 1 | 71-72 C10 grille | \$95.00 | \$95.00 |
| 1 | 71-72 C10 front bumper chrome | \$230.00 | \$230.00 |
| 1 | 67-72 C10 rear bumper chrome | \$230.00 | \$230.00 |
| 1 | 67-72 C10 rear bumper bracket set flt side or step side | \$61.00 | \$61.00 |
| 1 | 67-72 "push on" door seals from Precision Weatherstrip | \$60.00 | \$60.00 |
| 2 | 67-72 Glass run channel | \$10.00 | \$20.00 |
| 2 | 67-72 glass run channel LH or RH | \$13.00 | \$26.00 |
| 1 | 67-72 beltline molding kit (chrome) | \$37.00 | \$37.00 |
| 1 | 67-72 windshield weatherstrip seal without trim groove | \$36.00 | \$36.00 |
| 1 | 67-72 Rear window weatherstrip seal without trim groove | \$30.00 | \$30.00 |
| 1 | 67-72 outside door handle set L&R | \$55.00 | \$55.00 |
| 1 | 67-72 Drip rail molding set (stainless steel) | \$148.00 | \$148.00 |
| 1 | 71-72 Fuel neck grommet w/eec | \$7.00 | \$7.00 |
| 1 | 69-72 Chevy headlight bezel set w/screws L&R | \$48.00 | \$48.00 |
| 1 | 67-87 C10 license plate bracket edp coated | \$28.00 | \$28.00 |
| 1 | 67-87 C10 Rear License Plate Lamp Assembly | \$20.00 | \$20.00 |
| 1 | rear bumper bolt kit | \$15.00 | \$15.00 |
| 1 | front bumper bolt kit | \$15.00 | \$15.00 |
| 1 | Tail light bezel 69-72 Chevy & GMC Fleetside LH | \$16.50 | \$16.50 |
| 1 | Tail light bezel 69-72 Chevy & GMC Fleetside RH | \$16.50 | \$16.50 |
| 1 | Tail Light Bezel Clip Kit 69-72 Chevy & GMC Pickup & Suburban | \$8.00 | \$8.00 |

| | |
|-------------------|------------|
| Subtotal: | \$1,537.00 |
| Sales Tax: | \$107.60 |
| Total: | \$1,644.60 |

Parts will ship after the invoice has been paid in full.