

From:

Cooper Restorations
5304 S Adams
Marion, IN 46953
cooperrestorations@gmail.com

Invoice Number	CR-2405
Order Number	9382
Invoice Date	May 23, 2022
Total Due	\$3,584.63

Billing address

Kevin Piercefield
4725 N CR 650 W
Scipio, IN 47273

Hrs/Qty	Service	Rate/Price	Sub Total
1	67-72 C10 windshield tinted	\$175.00	\$175.00
1	67-72 windshield weatherstrip seal without trim groove	\$55.00	\$55.00
1	67-72 Rear window weatherstrip seal without trim groove	\$35.00	\$35.00
1	64-91 Door bumper set	\$4.00	\$4.00
1	Hood bumper (4 pcs)	\$4.00	\$4.00
1	67-72 Hood adjuster bolts (pr.)	\$5.00	\$5.00
1	Door and Ignition Lock Set	\$26.00	\$26.00
1	67-72 Ignition switch	\$14.00	\$14.00
1	67-71 C10 window regulator LH	\$37.80	\$37.80
1	67-71 C10 window regulator RH	\$37.80	\$37.80
1	67-72 C10 door latch LH	\$45.00	\$45.00
1	67-72 C10 door latch RH	\$45.00	\$45.00
1	67-72 LOCK AND RELAY ROD SET, W/CLIPS, 5PC, LH	\$20.00	\$20.00
1	67-72 LOCK AND RELAY ROD SET, W/CLIPS, 5PC, RH	\$20.00	\$20.00
1	67-72 "push on" door seals from Precision Weatherstrip	\$65.00	\$65.00
1	67-72 beltline molding kit (black)	\$53.00	\$53.00
2	67-72 glass run channel LH or RH	\$18.00	\$36.00
2	67-72 Glass run channel	\$12.50	\$25.00
1	69-70 "C10" Fender emblem set	\$40.50	\$40.50
1	American Autowire Complete Wiring Kit - 1969-72 Chevy Truck	\$619.00	\$619.00
1	67-72 C10 rear bumper chrome	\$304.00	\$304.00
1	rear bumper bolt kit	\$15.00	\$15.00
1	67-87 C10 Rear License Plate Lamp Assembly	\$20.00	\$20.00
1	71-72 C10 hood latch	\$61.00	\$61.00
1	67-72 molded urethane dash pads	\$65.00	\$65.00
1	67-72 C10 tailgate (fleet w/Chevrolet)	\$475.00	\$475.00
1	58-66 Tailgate Trunnions w/brackets	\$16.50	\$16.50
1	67-72 C10 tailgate latches (fleet)	\$52.75	\$52.75
1	67-72 C10 fleetside tailgate rods (pair)	\$13.50	\$13.50
1	67-72 C10 tailgate hinge set (L&R)	\$38.00	\$38.00
1	'67-'72 Low hump floor mat	\$168.75	\$168.75
1	60-72 Vent window repair kit	\$16.00	\$16.00
1	LH Tail Light Assembly 67-72 Chevy & GMC Fleetside	\$38.00	\$38.00
1	RH Tail Light Assembly 67-72 Chevy & GMC Fleetside	\$38.00	\$38.00
1	Back up lamp assy Lh	\$25.00	\$25.00
1	Back up lamp assy RH	\$25.00	\$25.00
1	69-72 Headlight adjuster kit	\$5.50	\$5.50
1	Grill to grill frame mounting kit	\$6.00	\$6.00
1	67-71 C10 inner door panel set (2 pcs) painted	\$102.00	\$102.00
2	67-72 C10 door sill plate w/kit, bowtie stainless	\$27.00	\$54.00

Hrs/Qty	Service	Rate/Price	Sub Total
1	67-72 C10 battery tray assy w/o air	\$59.50	\$59.50
1	67-72 Vent door assembly LH	\$61.00	\$61.00
1	67-72 Vent door assembly RH	\$61.00	\$61.00
1	66-71 Interior "day/night" rear view mirror	\$35.00	\$35.00
1	60-72 Brake and Clutch Pedal Pad (deluxe)	\$5.00	\$5.00
1	67-70 Accelerator Pedal (deluxe)	\$10.00	\$10.00
1	accelerator pedal ball studs	\$6.00	\$6.00
1	Stop light switch	\$6.00	\$6.00
1	67-72 C10 inner fender LH	\$102.75	\$102.75
1	67-72 C10 inner fender RH	\$102.75	\$102.75

Subtotal:	\$3,350.10
Sales Tax:	\$234.53
Total:	\$3,584.63

Parts will ship after the invoice has been paid in full.