



Invoice

From:
 Cooper Restorations
 5304 S Adams
 Marion, IN 46953
 cooperrestorations@gmail.com

Invoice Number	CR-2647
Order Number	10077
Invoice Date	October 29, 2022
Total Due	\$1,591.33

Billing address

Charlie Reed

Hrs/Qty	Service	Rate/Price	Sub Total
2	68-72 C10 rear side marker lamp red w/stainless trim	\$13.00	\$26.00
1	68-72 C10 frt side marker lamp amber w/trim	\$13.50	\$13.50
1	67-72 C10 rear bumper bracket set flt side or step side	\$65.00	\$65.00
1	67-87 C10 license plate bracket edp coated	\$33.70	\$33.70
1	rear bumper bolt kit	\$15.00	\$15.00
1	LH Tail Light Assembly 67-72 Chevy & GMC Fleetside	\$38.00	\$38.00
1	RH Tail Light Assembly 67-72 Chevy & GMC Fleetside	\$38.00	\$38.00
1	Back up lamp assy Lh	\$25.00	\$25.00
1	Back up lamp assy RH	\$25.00	\$25.00
1	Antenna kit	\$59.50	\$59.50
1	Tail light bezel 69-72 Chevy & GMC Fleetside LH	\$16.50	\$16.50
1	Tail light bezel 69-72 Chevy & GMC Fleetside RH	\$16.50	\$16.50
1	Tail Light Bezel Clip Kit 69-72 Chevy & GMC Pickup & Suburban	\$8.00	\$8.00
1	71-72 C10 chromed steel grille outer frame	\$743.00	\$743.00
1	71-72 C10 front bumper chrome	\$304.00	\$304.00
1	69-72 Headlight adjuster kit	\$5.50	\$5.50
1	69-72 Headlight bucket RH	\$25.00	\$25.00
1	62-68 Headlight mounting bucket	\$30.00	\$30.00

Subtotal:	\$1,487.20
Sales Tax:	\$104.13
Total:	\$1,591.33

Parts will ship after the invoice has been paid in full.