



Invoice

From:
 Cooper Restorations
 5304 S Adams
 Marion, IN 46953
 cooperrestorations@gmail.com

Invoice Number	CR-2675
Order Number	10167
Invoice Date	November 21, 2022
Total Due	\$928.76

Billing address
 Noah Freeman

Hrs/Qty	Service	Rate/Price	Sub Total
2	'73-'87 OE STYLE CAB FLOOR SUPPORT	\$19.00	\$38.00
1	81-87 C10 front inner fender LH	\$46.00	\$46.00
1	81-87 C10 front inner fender RH	\$46.00	\$46.00
1	81-91 HIGH QUALITY FRONT FENDER, LH	\$190.00	\$190.00
1	'81-'91 HIGH QUALITY FRONT FENDER, RH	\$190.00	\$190.00
1	'73-'87 WHEEL ARCH UPPER SECTION, DRIVER'S SIDE	\$19.00	\$19.00
1	'73-'87 WHEEL ARCH UPPER SECTION, PASSENGER'S SIDE	\$19.00	\$19.00
1	'73-'87 LOWER DOOR SKIN, DRIVER'S SIDE	\$26.00	\$26.00
1	'73-'87 LOWER DOOR SKIN, PASSENGER'S SIDE	\$26.00	\$26.00
1	'73-'91 (squarebody) DOOR BOTTOM WITH LOUVERS, DRIVER'S SIDE	\$45.00	\$45.00
1	'73-'91 (squarebody) DOOR BOTTOM WITH LOUVERS, PASSENGER'S SIDE	\$45.00	\$45.00
1	'73-'87 EXTENDED CAB FLOOR SECTION, LH	\$50.00	\$50.00
1	'73-'87 EXTENDED CAB FLOOR SECTION, RH	\$50.00	\$50.00
1	'73-'87 OEM STYLE ROCKER PANEL, DRIVER'S SIDE	\$30.00	\$30.00
1	'73-'87 OEM STYLE ROCKER PANEL, PASSENGER'S SIDE	\$30.00	\$30.00
1	'73-'87 ROCKER BACKING PLATE, DRIVER'S SIDE	\$9.00	\$9.00
1	'73-'87 ROCKER BACKING PLATE, PASSENGER'S SIDE	\$9.00	\$9.00

Subtotal:	\$868.00
Sales Tax:	\$60.76
Total:	\$928.76

Parts will ship after the invoice has been paid in full.