

**From:**

Cooper Restorations  
5304 S Adams  
Marion, IN 46953  
cooperrestorations@gmail.com

Invoice Number	CR-2936
Order Number	10913
Invoice Date	June 7, 2023
<b>Total Due</b>	<b>-\$-21.40</b>

**Billing address**

Joe Bandor  
11114 Maples Road  
Fort Wayne, IN 46816

Hrs/Qty	Service	Rate/Price	Sub Total
1	67-72 Midnite series brake booster/master cyl combo kit from CPP	\$389.00	\$389.00
1	64-91 Door bumper set	\$4.00	\$4.00
1	67-71 C10 front door relay, door latch short shaft (LH)	\$14.00	\$14.00
1	67-71 C10 front door relay, door latch short shaft (RH)	\$14.00	\$14.00
1	67-72 C10 door hinge lower LH	\$49.00	\$49.00
1	67-72 C10 door hinge lower RH	\$49.00	\$49.00
1	67-72 C10 door hinge upper LH	\$49.00	\$49.00
1	67-72 C10 Door hinge upper RH	\$49.00	\$49.00
1	67-72 C10 outside door handle LH	\$30.00	\$30.00
1	67-72 C10 outside door handle RH	\$30.00	\$30.00
1	67-72 LOCK AND RELAY ROD SET, W/CLIPS, 5PC, LH	\$20.00	\$20.00
1	67-72 LOCK AND RELAY ROD SET, W/CLIPS, 5PC, RH	\$20.00	\$20.00
2	47-72 Headlamp retaining ring	\$9.00	\$18.00
1	55-72 Window regulator retaining screw kit 16pc	\$6.50	\$6.50
1	67-72 front end bolt kit	\$40.00	\$40.00
1	67-72 Metal Bed Bolt kit (short fleetside)	\$50.00	\$50.00
1	62-68 headlight adj kit	\$12.00	\$12.00
1	67-68 Parking Light Assembly (front grill, LH)	\$50.00	\$50.00
1	67-68 Parking Light Assembly (front grill, RH)	\$50.00	\$50.00
1	Back up lamp assy Lh	\$25.00	\$25.00
1	Back up lamp assy RH	\$25.00	\$25.00
1	LH Tail Light Assembly 67-72 Chevy & GMC Fleetside	\$40.00	\$40.00
1	RH Tail Light Assembly 67-72 Chevy & GMC Fleetside	\$40.00	\$40.00
1	67-72 C10 inner door bottom LH	\$51.50	\$51.50
1	67-72 C10 inner door bottom RH	\$51.50	\$51.50
1	'67-'72 INNER FENDER TO FIREWALL "F" SHIM PACK, 2PC	\$16.50	\$16.50

<b>Subtotal:</b>	\$1,193.00
<b>Shipping:</b>	Local Pickup
<b>Sales Tax:</b>	\$83.53
<b>Payment method:</b>	Pay via Invoice
<b>Total:</b>	\$1,276.53

Parts will ship after the invoice has been paid in full.