

From:
Cooper Restorations
5304 S Adams
Marion, IN 46953
cooperrestorations@gmail.com

Invoice Number	CR-0504
Order Number	3061
Invoice Date	February 2, 2018
Total Due	\$4,116.00

Billing address **Shipping address**
Denny Jones N/A
23860

Hrs/Qty	Service	Rate/Price	Sub Total
1	69-72 Blazer bedside LH	\$715.00	\$715.00
1	69-72 Blazer bedside RH	\$715.00	\$715.00
1	67-72 C10 inner fender LH	\$68.00	\$68.00
1	67-72 C10 inner fender RH	\$68.00	\$68.00
1	69-72 C10 front fender driver side (LH)	\$170.00	\$170.00
1	69-72 C10 front fender passenger side (RH)	\$170.00	\$170.00
1	67-72 C10 tailgate (fleet w/Chevrolet)	\$330.00	\$330.00
1	67-72 C10 cowl panel	\$195.00	\$195.00
1	69-72 C10 cowl induction hood	\$480.00	\$480.00
1	69-72 C10 radiator support	\$175.00	\$175.00
1	67-72 C10 OE rocker panel 1.2mm LH	\$19.00	\$19.00
1	67-72 C10 OE rocker panel 1.2mm RH	\$19.00	\$19.00
1	69-72 Blazer/Jimmy rocker box LH	\$134.00	\$134.00
1	69-72 Blazer/Jimmy rocker box RH	\$134.00	\$134.00
1	69-72 Blazer/Jimmy rocker box end cap LH	\$45.00	\$45.00
1	69-72 Blazer/Jimmy rocker box end cap RH	\$45.00	\$45.00
1	67-72 C10 hood hinge w/o spring LH	\$35.00	\$35.00
1	67-72 C10 hood hinge w/o spring RH	\$35.00	\$35.00
1	67-72 Hood Hinge Spring Set	\$25.00	\$25.00
1	LH Tail Light Assembly 67-72 Chevy & GMC Fleetside	\$35.00	\$35.00
1	RH Tail Light Assembly 67-72 Chevy & GMC Fleetside	\$35.00	\$35.00
1	Back up lamp assy Lh	\$25.00	\$25.00
1	Back up lamp assy RH	\$25.00	\$25.00
1	69-72 headlight bucket LH	\$30.00	\$30.00
1	69-72 Headlight bucket RH	\$30.00	\$30.00
1	67-72 C10 outer cab floor ext LH	\$62.00	\$62.00
1	67-72 C10 outer cab floor ext RH	\$62.00	\$62.00

Subtotal:	\$3,881.00
Shipping:	\$235.00 via Shipping
Total:	\$4,116.00