

From:

Cooper Restorations
5304 S Adams
Marion, IN 46953
cooperrestorations@gmail.com

Invoice Number	CR-2348
Order Number	9192
Invoice Date	April 16, 2022
Total Due	\$1,771.17

Billing address

Tim Kleignknight

Hrs/Qty	Service	Rate/Price	Sub Total
2	68-71 Armrest Green (each)	\$25.00	\$50.00
1	67-72 Cargo light harness	\$20.00	\$20.00
1	67-71 C10 window regulator LH	\$37.80	\$37.80
1	67-71 C10 window regulator RH	\$37.80	\$37.80
1	67-72 Door Striker Plates (pair)	\$30.00	\$30.00
1	69-70 C10 inner grille	\$106.75	\$106.75
1	68-72 Rear window molding kit	\$55.00	\$55.00
1	68-72 C10 vent window assy w/tinted glass LH	\$305.00	\$305.00
1	68-72 C10 vent window assy w/tinted glass RH	\$305.00	\$305.00
2	68-76 C10 door window crank (black)	\$5.00	\$10.00
2	67-72 windshield wiper arm	\$15.75	\$31.50
2	67-72 wiper blade	\$15.00	\$30.00
1	67-71 C10 front door relay, door latch short shaft (LH)	\$14.00	\$14.00
1	67-71 C10 front door relay, door latch short shaft (RH)	\$14.00	\$14.00
1	Upper Tailgate Molding Clip Kit 67-72 Chevy & GMC Fleetside	\$8.00	\$8.00
2	Door relay screw kit	\$3.00	\$6.00
2	68-72 C10 door handle inside	\$5.50	\$11.00
1	67-72 Door lock knob set (chrome)	\$7.00	\$7.00
1	64-91 Door bumper set	\$4.00	\$4.00
2	Tail/backup Lens screw	\$2.00	\$4.00
1	67-71 Door panel screw set	\$3.00	\$3.00
1	60-72 Rocker Panel Plug Set.	\$3.00	\$3.00
1	69-72 Headlight adjuster kit	\$5.50	\$5.50
1	67-71 frt upper door panel trim chr L&R (pair)	\$88.00	\$88.00
1	67-72 INNER FENDER TO CAB BOLT W/CONVEX WASHER	\$12.85	\$12.85
2	door panel seal	\$5.00	\$10.00
1	67-72 C10 windshield tinted	\$175.00	\$175.00
2	side window glass and track	\$135.00	\$270.00
1	67-72 Rear window glass (large) w/green tint	\$145.00	\$145.00
1	67-72 LOCK AND RELAY ROD SET, W/CLIPS, 5PC, LH	\$20.00	\$20.00
1	67-72 LOCK AND RELAY ROD SET, W/CLIPS, 5PC, RH	\$20.00	\$20.00

Subtotal:	\$1,839.20
Discount:	-\$183.92
Sales Tax:	\$115.89
Total:	\$1,771.17

Parts will ship after the invoice has been paid in full.